

NOTE:

(59) SUPPLY 25' OF COAX LOOSE WITH MALE PLUG ON EACH END.

(57) PUT MALE PLUG ON TOP END AND FEMALE PLUG ON BOTTOM END OF 45' COAX INSTALLED IN MAST.

USE 1-1/2" OD PVC TUBE.

USE 12 GA. WIRE ONLY.

INSULATE UNDER ALL TANGS & STAINLESS STEEL HARDWARE WITH BLACK VINYL TAPE.

USE LANOCOTE ON ALL FASTENERS.

CHECK MAST STEP FOR FIT BEFORE SHIPPING.

Top of Deck
BOX 7'-7" above Heel

I _____ J 17'3" P 32'6" E 14'8" BAR 4'2" BURY 5'11" JOB NUMBER _____

A	Spreader Arm	879650 (2)	Taper 20" SPR 1
B	" Tip	837410 (2)	
C	" CLEVIS	854312 (4)	
D	" Light	(2)	
E	Flag Block OP	855100 (2)	
F	" " Eye OP	855010 (2)	
G			
H			



L	Spreader Arm	879650 (2)	Taper 20" SPR 2
M	" Tip	837410 (2)	
N	" CLEVIS	854312 (4)